

Maxford USA Antonov An-2 Incident, August 9, 2013

### **Parts recovered and removed at the field**

broken APC 13x8E prop

cowl - broken plastic air scoop and dummy engine, lots of cracks in the fiberglass cowl

broken motor mount box - parts gathered and bagged

removed the left wing panels

### **At home**

Noted that the ESC wires ran up through the bottom right of the motor box and out the right side

removed the O.S. Motor OMA-5010-810 motor

removed the Castle Creations Ice 50 ESC noting that 3 short cable ties made up the strap, the receiver lead ran through the bottom left hole in the former and power leads through the top left hole - no apparent damage to the ESC

removed the 4S "A123" 2300mAh battery - no apparent damage

removed right wing panels

removed top center section - plastic top had small cracks at the front and rear of right side - only cosmetic damage

removed lower wing rods

both lower wing fairings were loose - removed them

Noted damage to lower, right bottom wing fairing - the 3/4" square 1/16" ply had pulled away a bit from the wood of the fairing bottom

Both rear landing gear wires were slightly bent - straightened them by hand

Noted that the main gear collets were not in the correct position and gear at an 'odd' angle

Tactic TR624 receiver removed - installed in the Thunder Tiger Lazy Tiger Cub trainer plane and flown successfully on 8/10/2013.

Mounted power system to the test stand - the prop adapter and/or shaft appeared bent on the run up - ordered prop adapter and shaft from Tower Hobbies

Started piecing together the 'jigsaw puzzle' of the motor mount box

hooked up the Tactic TR624 out of the 'Cub' with a receiver battery and checked all servos for possible stripping - all six servos checked out okay.

removed the broken strut from the top and bottom left wing panels - strut was not 'broken' but had separated at a glue joint

Noted a lot of damage at the root rib of the top left wing panel - the wood part that attaches the wing to the center section using the Maxlok key was out of the wing and had been bagged at the field - no real glue on the piece

Noted that I should attach the bottom of the wing struts first when putting the panels back together because of the angle

removed the strut from the top and bottom right wing panels even though there was no damage to the strut - need to work on the top right panel and stripe the strut to match the strip going on the left strut to cover the repair

started the repair of the top left panel - had to go purchase thin CA

continued work on piecing and gluing the motor mount box

Used Titebond to repair the lower, right fairing Maxlok hole reinforcement plywood

glued seams of the cracks in the center top section with Aleene's Original Tacky Glue which appears to be about the same as RC-56 - dries clear and has the same smell after glue dried removed tape from all parts  
finished the motor mount box repair  
moved and retightened the main gear wheel collars inside the fuselage  
cleaned bottom wing fairings for a better fit  
added a little masking tape to the bottom wing rods so they didn't move so easily  
bottom wing panels inspected again and found to be okay - then trial fitted to the wing fairings  
covering was removed from the wing fairing area on the fuselage - Titebond used to attach fairings - taped in place - more Titebond added into the fairing joint using a syringe once original had dried  
repaired top left wing panel root area, with the most damage, and glued the Maxlok tab even gluing to the bottom wing sheeting - the butt joint and joint where it exited the wing was just not secure enough  
removed the tape from the lower wing fairings  
repaired the top right wing panel and secured the Maxlok key holder piece to the bottom sheeting  
Sanded the filler used on the top of the top left wing panel  
Measured the 'angle' on the new motor mount due to the box being crooked - about 1/8" off  
1/16", 3/32" and 1/8" plywood shims were made for use when remounting the motor  
Repaired the cowl - fiberglass 'cracks' were painted with Testors gloss black and red, air scoop missing plastic covered with masking tape and painted gloss black, dummy engine glued as well as could be with a lot of missing parts  
covered the top and bottom of the top wing repairs with red covering and ironed down some wrinkles in the front of the fuselage  
covered the reglued strut joint with a red strip and put a matching stripe on the other strut  
attached the aileron and flap extensions the TR624  
reinstalled the center section  
attached rudder and elevator servos and verified all working correctly using a receiver battery  
reattached the struts the bottom panels first and then the tops - a magnet proved very helpful  
attached the wing panels and checked all servos for correct throw again  
replaced the shaft and prop adapter\*  
tested power system on the test stand with new prop  
reinstalled the battery and ESC  
Reinstalled the motor using the 1/16" shim on the right side and a washer under each top leg of the "+" for down thrust  
Took plane outside and tested the power system with the fully charged 4S "A123" 2300mAh battery - the numbers were quite different from the original power test - it was a different prop (APC has had various iterations of props labeled the same) and the temperature was about 20-deg C cooler - results of test: 11.12v, 38.1 amps, 7074 RPM and 424 watts in

radio system range tested from different angles - checked okay  
replaced batteries in the Tactic TTX650 - just to be sure, although not showing low  
attached the cowl  
checked the balance - okay

### **August 16, 2013**

plane to the field and photographed with repairs  
flown very successfully three times - all flights ended with the plane on its wheels -  
really nice landings  
slight trim change needed on ailerons  
more down elevator required  
plane climbs quite rapidly with no elevator input at full throttle  
most flying done with throttle stick on transmitter just about 1/2

### **At home**

two more washers, for a total of 3, added for more down thrust

### **replaced the shaft and prop adapter\***

That is a simple enough statement. Unfortunately, it was not simple.

When I took the OMA-5010-810 apart I found it to be a very well made product. I've opened up several outrunners in my lifetime, and I've got to say that the engineering and production execution was excellent!

I had a problem replacing the shaft. I broke the metric socket head cap screw on the back of the motor.

(<http://www3.towerhobbies.com/cgi-bin/wti0001p?&l=LXCRNB&P=7>

Price \$4.99 for a single screw)

I tried to loosen it both ways, as I thought it might have reverse threads on it. It would not budge either way and I eventually applied enough force to break the head off the screw.

After I broke the screw, I carefully looked at the threads on the new shaft, and they appeared to me to be 'reverse' threaded.

There were no local sources available to me for the 4x10mm reverse thread screw.

The fix was to tap the shaft for a standard 6-32 thread and use a 6-32 bolt and washer and blue Locktite it in.